



RELEASED  
20.10.07

JRB

PPP

Part Number	D119-796-025
Description	STD Landing Gear w/ Training Wearplates

Box Part Number		
Other Packaging		
Logo Decals		

### Packaging Instructions and Decal Placement

#### D119-796-025

Remove Lid and Front Panel from crate.

Add 4x MF668 and MF166 foam to all four corners inside to prevent rubbing on walls.

Place landing gear in crate with help from others.

Cut 8 blocks of wood at 4x4x2". In all corners, screw one block to the floor and one block to the wall.

Add 4 pcss of metal strapping at 12" long and 4 pcs of rubber guard (D2182) wrapped around metal.

Add white foam to the landing gear and screw metal strapping and rubber guard inot the wood blocks located on the floor and wall to secure parts in place (Screw through rubber to ensure it does not slip off metal).


Ensure metal straps and rubber guards are well placed and tight but will not damage landing gear.

Triple check packaging, close front panel of the crate. Fill any gaps with foam.

Reinstall the lid.

Add appropriate caution and Plex labels and documents.

**DO NOT ATTEMPT TO MOVE CRATE WITHOUT FORK EXTENSIONS AND SPOTTER.**



D2729-4

D2729-3

N/A

<b>DART</b> AEROSPACE			
1000 ALCOCK RD HAWTHORNE, ONT. CANADA M6A 1K2 TEL: 416-882-1100 FAX: 416-882-1101			
PATENT	N/A	CHG	CHG003
P.N.	D119-796-025	STC	SH14-45
DESC	STD Gear w/ Training Wearplate	STC	SR03504NY
LOT	SXXXXXX	STC	
MODEL	AW119 MKII	STC	
TC APPROVAL # 09-89		MADE IN CANADA	

*She Evans*

OCT 07 2020

Revision: C  
Date: 20.10.07